



Optional Spare Parts For Lathe Machine



A01. 3-jaw Chuck



A02. 4-jaw Chuck



A03. Follow Rest



A04. Steady Rest



A05. 40 POS. Tool Post Set



A06. Live Center



A07. Tailstock Chuck



A08. 5C Collet Chuck



A09. Thread Chasing Dial



A10. Face plate



A11. Cutter Set



A12. Quick Change Tool Post



A13. Digital Readout



A14. Universal Coolant System



A15. Lathe Tool Kit



A16. Powerful Motor



A17. Halogen Lamp



A18. Collet Kit



A19. Clamping Kit



A20. Machine Base





Optional Spare Parts For Milling Machine



B01. Keyless Drill Chuck



B02. Face Mill



B03. Mill Chuck Set



B04. Reversible Tapping Chuck



B05. HSS End Mill Set



B06. Clamping Kit



B07. Precision Toolmaker's Vice



B08. Power Feed



B09. Milling Vice



B10. Premium Machine Vice



B11. 2-Axis Tilting Vice



B12. 3-Axis Tilting Vice



B13. Digital Position Display



B14. Magnetic Chuck



B15. Hydraulic Machine Vice



B16. Universal Machine Vice



B17. Dividing Head Set



B18. H/V Rotary Table



B19. Coolant Pump System



B20. Heavy Stand





Optional Spare Parts For Metalworking Machine



C01. Digital Micrometer




C02. Saw Band



C03. Digital Caliper



C04. Morse Taper



C05. Drill Bit Set



C06. HSS Twist Drill with Morse Taper



C07. Magnetic V-Block



C08. Precision Parallel Block



C09. Bench Vise W/ Anvil



C10. Tilting Angle Vise



C11. Precision Universal Vise



C12. Quick Release Vise



C13. Digital Depth Gage



C14. Toolmaker Machine Vise



C15. Parrot Vise



C16. Machine Vise



C17. Quick Drill Chuck



C18. Circular Saw Blade



C19. Toolmaker's Steel Vise



C20. Universal Dividing Head





Optional Spare Parts For Metalworking Machine



D01. Cross Table



D02. Cross Table With Power Feed



D03. Cross Table with Stepper Motor



D04. Power Feed



D05. Swivelable Rotary Table



D06. H/V Rotary Table With Chuck



D07. Tailstock



D08. Adjust Swivel Table



D09. Angle Vise



D10. Cross Sliding Vise



D11. Vibration Damper



D12. Digital Height Gage



D13. V-Block & Clamp Set



D14. Stepper Motor



D15. Boring Head Set



D16. Extension Socket



D17. Test Indicator



D18. Drilling Machine Vise



D19. Drill Chuck Arbor



D20. Magnetic Base





Optional Spare Parts For Metalworking Machine



E01. 3-Axis Digital Position Indicator Set



E02. Universal Power Vice



E03. High Precision Double Clamp Milling Vice



E04. Gage Block Set



E05. 2-Axis Digital Position Indicator Set



E06. Carbide Turning Tool Set

